


Figure 1. Weight change during the oxidation of steel and copper in $40\%O_2$ /Ar at 500 °C.






Figure 2. Copper (a) and steel (b) after oxidation in air at 700 °C.




Figure 3. Weight change of copper and steel during oxidation in air at 500 $^{\circ}$ C under thermal cycle.




Figure 4. Copper wire after oxidation in air at 700 °C.




Figure 5. CaO- SiO_2 - B_2O_3 phase diagram.




Figure 6. (a) steel rod wound copper wire and (b) steel rod after dissolution of copper oxide.




FIGURE 7




FIGURE 8